



НЕОБХОДИМЫЕ ИНСТРУМЕНТЫ



СПИСОК ДЕТАЛЕЙ

X2	X1	X1	X1	X1	X1	X1	X2
X1	X2	X1	X1	X2	X1	X1	X1
				X2			X10
4x30	X8	4x16	X2	X2			X10

1

Размеры (мм)	A (мм)
800x800x1950	785-800
900x900x1950	885-900
1000x1000x1950	985-1000

2

3

4

5

6

